

The diagram illustrates a rectangular assembly with the following components and features:

- 10**: Points to the top-left corner of the main rectangular frame.
- 40**: Points to the top edge of the main rectangular frame.
- 70**: Points to a horizontal line of 'X' marks within the upper section of the rectangle.
- 80**: Points to a horizontal line of 'X' marks within the middle section of the rectangle.
- 90**: Points to a horizontal line of 'X' marks within the lower section of the rectangle.
- 100**: Points to a horizontal line of 'X' marks within the bottom section of the rectangle.
- 110**: Points to a horizontal line of 'X' marks within the very bottom section of the rectangle.
- 20**: Points to the left edge of the main rectangular frame.
- 30**: Points to the right edge of the main rectangular frame.
- 50**: Points to the bottom edge of the main rectangular frame.
- 60**: Points to a diagonal line extending from the right side of the rectangle.
- 120**: Points to a triangular shape located at the top-right corner of the rectangle.

50

FIG 2




FIG 3




FIG 4




FIG 5




FIG 5A

